

Date: 5/16/2025

Region: 4A

FEMS No.: 3156542

FAC ID: NY126

Maximo WO No.: 18839

Asset #: NA

Priority: Urgent



**Original Work Request:**

The timer that controls the exterior lights on the OMS building is not working. The lights do not turn on when the timer is set to AUTO. The lights work and the timer is now set to HAND. This means the lights are on 24/7. The lights need to be on as it is a security issue.

**Description of Repairs Needed:**

Labor and material to troubleshoot and repair exterior light control timer for VMS building and lot.

**Labor:**

	Labor Hrs	Labor Rate	Total
Service Technician	8	\$ 100.00	\$ 800.00
			\$ -

**Material List:**

Material	Quantity	Cost	Total
	1	\$ 25.00	\$ 25.00
			\$ -
			\$ -
			\$ -

**Equipment List:**

	Quantity	Cost	Total
			\$ -
			\$ -
			\$ -

**PM WO History:**

NA

**Estimate Summary:**

Labor	Material	Equipment
\$ 800.00	\$ 25.00	\$ 0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$825.00	\$99.00	\$49.50	\$973.50

**HUNOLD CONTRACTING INC.**  
72 PENDERGAST ROAD  
PHOENIX, NY 13135  
Cell # 315-247-5898

Customer:

Tidewater Attn: JuliePape  
6625 Selmick Dr., Suite A  
Elkridge, MD 21075

**ESTIMATE**  
**5/15/25**

<b>Quantity</b>	<b>Description</b>	<b>Amount</b>
1	FEMS 3156542, WO 18839, NY126 Chili, NY  Troubleshoot and repair exterior light control timer for VMS building and lot.  Material: (\$25) Labor: (8 hours @\$100/ hr.) = \$800	<b>825.00</b>
		<b>Sub total</b> <b>825.00</b>
		<b>Sales Tax</b> <b>N/A</b>
		<b>Total</b> <b>825.00</b>

Signature \_\_\_\_\_ Date \_\_\_\_\_

Signature \_\_\_\_\_ Date \_\_\_\_\_