

Additional Funding Request

Site: WV009	WO# 6862 CSS # 16725 Asset# NA
Description of Repairs	Repair high hanging heater in the wash bay.
Diagnosis: Initial Work Order CSS# 16725	Repair high hanging heater in the wash bay.
Explanation of Additional Costs for Repairs	Investment is labor and lift rental to inspect issues with gas heaters in the Wash Bay located at USARC Clarksburg, WV009, CSS# 16725. If repairs are needed another quote will follow.
Additional Labor Cost to Perform Repairs	Mechanic- 8 x \$115= \$920.00 Apprentice- 8 x \$93= \$744.00
Additional Material Cost to Perform Repairs	\$280.50
Total Cost of Repair	\$1,944.50

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: WV009 AMSA 102-G
269 ARMORY RD.
CLARKSBURG, WV. 26301

Date of Visit: 12/14/18

Contractor Personnel on Site:

1. Steve Tregear 2. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO# 155249

Service Calls – Service Call Number and Description

1. CSS# 16473
2. CSS# _____
3. CSS# _____

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Steve Tregear Date: 12/14/18

Signed: [Signature]

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: John E. Cassidy WG09 Date: 14 DEC 18

Signed: [Signature]

E-Mail: John.E.Cassidy@wv.gov

