

## Additional Funding Request

<b>Site: WV046</b>	<b>WO# 6448</b>	<b>CSS # 16259</b>	<b>Asset# NA</b>
Description of Repairs	Install dedicated circuit to exhaust fan		
Diagnosis: Initial Work Order <b>CSS# 16259</b>	<p>The exhaust fan in the motor pool battery room and exhaust fan in the OMS mechanical Room trip the breaker when turned on.</p> <p>Both fans are on the same circuit. Troubleshoot fans and circuit to determine cause of breaker trip</p>		
Explanation of Additional Costs for Repairs	Labor and material to install dedicated circuit to exhaust fan		
Additional Labor Cost to Perform Repairs	\$1,047.66		
Additional Material Cost to Perform Repairs	\$292.79		
Total Cost of Repair	\$1,340.45 + \$329.37 (Incurred)= \$1,669.82		

## CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: WV 046 Date of Visit: 2.28.19

#### Contractor Personnel on Site:

1. Elco Rockey 2.

Work Performed: Check to see what's causing breaker to trip in battery Rm

**Preventive Maintenance - (Annual, Quarterly, Monthly, equipment identification, etc.)**  
**Service Orders - CSS# 16259**

## CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Ricky Hicks Date: 2-28-19

Signed: Ruth Park

To be signed by Facility Manager:

I certify that the above-named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: Dwayne FeHon W603 Date: Feb 28, 2019

Signed: 

E-Mail: dwayne.a.felton4.civ@mail.mil

