



Found while performing the Vault PM.

S&G 2937 dial lock to be replaced at WV 014 – Current lock will not spin or read numbers - Must be replaced immediately

ADVANCED SECURITY SAFE & LOCK
6318 REISTERSTOWN RD
BALTIMORE, MD 21215

Tel: (410) 764-2001
Tel: (877) 267-6562
Fax: (410) 561-6031
Email: Billing2@ampmlock.com
www.AMPMLOCK.com



Estimate

Date	Estimate #
7/29/2019	28958

Customer Information
ISG 16800 Imperial Valley Drive Huston, TX 77060 Mike Merchan

Item	Description	Qty	Cost	Total
S&G Dail Lock	S&G 2937 dial lock to be replaced at WV 014 - Current lock will not speen or read numbers - Must be replaced immediatly list price \$713.00	1	860.00	860.00
LABOR	Labor to Remove existing lock and install the new lock	1	750.00	750.00

WE LOOK FORWARD TO ASSISTING YOU!

Advanced Security Safe & Lock's One Year Warranty on recalls only covers parts and services/labor when the part is provided by Advanced Security Safe & Lock. Service/labor on parts not provided by Advanced Security Safe & Lock or if the parts have passed the one year warranty time period are NOT covered under Advanced Security Safe & Lock's One Year Warranty.

SIGNATURE: _____

DATE: _____

Terms: 50% deposit and 50% due upon completion

Subtotal	\$1,610.00
Sales Tax (0.0%)	\$0.00
Total	\$1,610.00