

## Additional Funding Request

<b>NY126</b>	<b>CSS# 17769 WO# 8152 Asset# 7576</b>											
Description of Repairs	Labor and materials to repair gate rollers on manual drive through gate.											
Diagnosis: Initial Work Order	Make repairs to gate rollers on manual drive through gate. Rollers are in disrepair and cause gate to come off track. Routine request.											
Diagnostic Fee	<p>\$ 160.00</p> <p>TW Labor \$80/hr x 2</p>											
Additional Labor Cost to Perform Repairs	<p>\$ 320</p> <p>TW Labor \$80/hr x 4</p>											
Additional Material Cost to Perform Repairs	<p>\$413.10</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">2-4" Nylon Cantilever Rollers</td> <td style="width: 15%; text-align: center;">2</td> <td style="width: 15%; text-align: center;">\$194.40</td> <td style="width: 20%; text-align: center;">\$388.80</td> </tr> <tr> <td>Sales Tax</td> <td></td> <td></td> <td style="text-align: center;">\$24.30</td> </tr> </table>				2-4" Nylon Cantilever Rollers	2	\$194.40	\$388.80	Sales Tax			\$24.30
2-4" Nylon Cantilever Rollers	2	\$194.40	\$388.80									
Sales Tax			\$24.30									
Total Cost of Repair	\$ 893.10											



