

Additional Funding Request

Site: WV009	WO#7211	CSS # 17152	Asset# NA
Description of Repairs	Repair Roof Exhaust Fan in Welding Bay		
Diagnosis: Initial Work Order CSS# 17152	Exhaust Fan INOP		
Explanation of Additional Costs for Repairs	Labor and material to investigate the INOP roof exhaust fan		
Additional Labor Cost to Perform Repairs	Mechanic- \$115 x 8= \$920.00 Apprentice- \$93 x 8= \$744.00		
Additional Material Cost to Perform Repairs	Trip Charge- \$35.00		
Total Cost of Repair	\$1,699.00		

CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: WV009

Date of Visit: 1/14/2019

Contractor Personnel on Site:

1. Steve Tregear

2. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO# 155843

Service Calls – Service Call Number and Description

1. CSS# 17152
2. CSS# _____
3. CSS# _____

CERTIFICATION OF WORK

To be signed by the Contractor:


Print Name: Steve Tregear Date: 1/14/2019

Signed: 

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: Karen Y Hill GS7 Date: 1/14/2019

Signed: 

E-Mail: karen.y.hill2.civ@mail.mil

