



Urinal nearest the showers is leaking at wall face when flushed. Make repairs as required and check all other plumbing devices for proper operation in training building and OMS. Adjust flows to fountains to proper height and flow. Check toilets, urinals, faucets etc for proper operation and for leaks.

Proposal is to remove and replace the faucet from the mop sink.

CMI Cost Estimate								
Funding Request								
PA052 Johnstown								
Urinal nearest the showers is leaking								
CSS #16523 - CMI # 6810								
Prepared By: J. Bayne								
1.07.19								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
1. Repair Cost								
1.1 Labor	\$ 98.00	4						\$ 392.00
1.2 Pressure Relief valve					\$ -	\$ -	\$ -	\$ 194.87
Sub Total Repair Cost								\$ 586.87
2. Initial Service Call Investigation								
2.1 Field Review at Site	\$ 98.00	3						\$ 294.00
Grand Total								\$ 880.87