



Repair AHU in Heated Storage bldg. NO HEAT. Troubleshoot and repair in order to restore heat function.

Proposal is to provide and install 2 Trane sensors for the AHU.

CMI Cost Estimate								
Funding Request								
PA166 Coraopolis								
Repair AHU in Heated Storage bldg.								
CSS #17041 - CMI # 7177								
Prepared By: J. Bayne								
1.18.19								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
1. Repair Cost								
1.1 Labor	\$ 98.00	2.5						\$ 245.00
1.2 Material					\$ -	\$ -	\$ -	\$ 65.41
1.3 Shipping								\$ 24.00
Sub Total Repair Cost								\$ 334.41
2. Initial Service Call Investigation								
2.1 Field Review at Site	\$ 98.00	4						\$ 392.00
Grand Total								\$ 726.41