

Additional Funding Request

NY032	CSS# 17565 WO# 7564 Asset# NA
Description of Repairs	Labor to remove AIR from heating system.
Diagnosis: Initial Work Order	Remove air from heating loop. Drill hall at NY032 is not getting heat. Recommended vendor is Monroe Piping. Urgent Request
Diagnostic Fee	\$0
Additional Labor Cost to Perform Repairs	\$ 900.72 MP&SM LLC Labor \$112.59/hr x 8
Total Cost of Repair	\$ 900.72