



Asset# 4653- Unit heater is inoperable due to faulty fan motor. Request is for vendor to replace fan motor.

Proposal to provide and perform the following:

- Properly remove defective fan motor
- Provide and install Fan Motor
- Provide and install Fan Blade
- Control Variable Speed Motor
- Start up
- Warranty

CMI Cost Estimate								
Funding Request								
WV041 Weirton								
Unit heater is inoperable due to faulty fan motor								
CSS #17090 - CMI # 7143								
Prepared By: J. Bayne								
02.05.19								
Asset # 4653								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
1. Repair Cost								
1.1 Labor	\$ 98.00	4						\$ 392.00
1.2 fan motor, fan blade, variable speed					\$ -	\$ -	\$ -	\$ 648.66
1.3 Shipping								\$ 24.00
Sub Total Repair Cost								\$ 1,064.66
2. Initial Service Call Investigation								
2.1 Field Review at Site	\$ 98.00	1.5						\$ 147.00
Grand Total								\$ 1,211.66