



Heating radiator located in admin area of OMS is inoperable. Request is for vendor to troubleshoot and make needed repairs.

Proposal to provide and perform the following:

- Remove Defective Pressure Regulator
- Provide and install (1) B&G Pressure Regulator
- Start up
- Warranty

CMI Cost Estimate								
Funding Request								
WV038								
- Heating radiator located in admin area								
CSS #17272 - CMI #								
Prepared By: J. Bayne								
02.13.19								
P3								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
1. Repair Cost								
1.1 Labor	\$ 98.00	8						\$ 784.00
1.2 Pressure Regulator					\$ -	\$ -	\$ -	\$ 106.82
1.3 Fittings / pipe dope								\$50.00
1.4 Shipping								\$ 24.00
Sub Total Repair Cost								\$ 964.82
2. Initial Service Call Investigation								
2.1 Field Review at Site	\$ 98.00	4.5						\$ 441.00
Grand Total								\$ 1,405.82