



Repair the following electrical issues:

1) Rm 127- issue with power coming out of surface mounted supply 2) Kitchen -occupancy sensor in kitchen latrine not working 3) Rm 107 - loose blankjunction box cover 4) Rm 110 - issues with power supply to outlets – Outletto right of doorway (as enter room) does not work 5) Rm 203 - conduit andoutlet separated from wall 6) Mech Rm - emergency light over mechanical roomexterior doors not working 7) emergency light outside of AHU 3 area notworking 8) Rm 203 - outlet on R side of room - ground port is obstructed intop outlet.

Proposal for electrical repairs.

*Kitchen Latrine – replace motion sensor

*Room 110 – repair power to outlet

*Room 107 – tighten cover

*Room 203 – remove outlet & conduit

*Room 127 – repair power to outlet

*Mechanical Room – replace ext/emergency sign

*AHU 3 Area – replace emergency light

*Room 203 – replace outlet

CMI Cost Estimate								
Funding Request								
PA079								
Remove & replace pressure relief valve								
CSS #13713 - CMI # 7508								
Prepared By: J. Bayne								
02.15.19								
Routine								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
1. Repair Cost								
1.1 Labor	\$ 75.00	8.75						\$ 656.25
1.2 Material					\$ -	\$ -	\$ -	\$ 162.81
Sub Total Repair Cost								\$ 819.06
2. Initial Service Call Investigation								
2.1 Field Review at Site	75	3						\$ 225.00
2.2 Truck Charge								
Grand Total								\$ 1,044.06