



PA051 building 204- Repair P-TAC unit, blowing fuses inside unit in heating mode. PA051-19402 Asset #4657

Proposal to provide and perform the following:

- Properly remove old defective PTAC Unit
- Provide and install (1) Sea Breeze PTAC Unit
- Start up
- Warranty

CMI Cost Estimate								
Funding Request								
PA051-194 Johnstown								
Building 204- Repair P-TAC unit								
CSS #17317 - CMI # 7503								
Prepared By: J. Bayne								
02.06.19								
Asset # 4657								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
1. Repair Cost								
1.1 Labor	\$ 98.00	6						\$ 588.00
1.2 Pressure Relief valve					\$ -	\$ -	\$ -	\$ 1,003.98
1.3 Shipping								\$ 24.00
Sub Total Repair Cost								\$ 1,615.98
2. Initial Service Call Investigation								
2.1 Field Review at Site	\$ 98.00	4						\$ 392.00
Grand Total								\$ 2,007.98