



Floor drain located in facility kitchen has become clogged. When dishwasher is used, drains back up and cause water to accumulate on kitchen floor. Request is for vendor to clear all floor drains in both the kitchen AND mechanical room.

Proposal to provide and perform the following:

- Re-route dishwasher drain line to floor drain next to the dishwasher. Floor drain currently routed to is corroded shut and can't get the snake past the trap.

CMI Cost Estimate								
Funding Request								
FR PA096 Washington								
Floor drain located in facility kitchen								
CSS #15130 - CMI # 7535								
Prepared By: J. Bayne								
02.07.19								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
1. Repair Cost								
1.1 Labor	\$ 98.00	4						\$ 392.00
1.2 Material								\$ 101.71
Sub Total Repair Cost								\$ 493.71
2. Initial Service Call Investigation								
2.1 Field Review at Site	\$ 98.00	2.5						\$ 245.00
Grand Total								\$ 738.71