

CSS 17322- PA013- Routine- Evaluate the condition of the window AC units in the ARC. Vents are showing signs of mildew growth. Determine the extent that this growth has affected the internal areas of the units. Can it be cleaned/remediated in order to keep the units in operation or are they so far gone that the growth will be a recurring issue and have a negative impact on air quality in the facility?

CMI Cost Estimate				
Window AC Units				
PA013 Butler				
CSS #17322 - CMI #7540				
Prepared By: B. Koblinsky				
Date: 2.14.19				
Description	Unit	Quantity	Sub- total	Total Cost
Labor Straight Time	\$625.00	18		\$11,250.00
Workstation Setup	\$1,500.00	1	\$ 1,500.00	
Sub-Total			\$ 1,500.00	\$1,500.00
Total				\$12,750.00