



Repair lighting issues: 1) exit sign with lights over exterior doors in mechanical room not working - install operational fixture; 2) emergency light by Rm 104 in drill hall does not illuminate when tested - troubleshoot and make necessary repair; 3) LED wall pack over kitchen exterior man door - marginally illuminated (left side only); 4) LED wall pack to right of entrance by flagpole - marginally illuminated (right side only); and 5) wall pack to left of entrance by flagpole - marginally illuminated. (Items 3 through 5 are suspected to be faulty LEDs and not drivers).

Proposal is to make repairs listed below.

Replace one exit sign located in mechanical room.

Replace one emergency light in room 104

Troubleshoot three wall packs on outside of building, (Suspect bad LED's)

CMI Cost Estimate								
Funding Request								
PA011								
Repair lighting issues								
CSS #17316 - CMI # 7545								
Prepared By: J. Bayne								
02.14.19								
P3								