



- Prepare project site for installation
- Remove urinal for the wall
- Snake out urinal drain as necessary
- Re-Install urinal
- Verify proper operation of drain.

CMI Cost Estimate								
Funding Request								
WV053 Wheeling								
2 out of 3 urinals in Men's latrine								
CSS #15613 - CMI # 5918								
Prepared By: J. Bayne								
1.17.19								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
1. Repair Cost								
1.1 Labor	\$ 98.00	8						\$ 784.00
1.2 Consumables					\$ -	\$ -	\$ -	\$ 30.00
Sub Total Repair Cost								\$ 814.00
2. Initial Service Call Investigation								
2.1 Field Review at Site								\$ 450.00
Grand Total								\$ 1,264.00