



PA051-Building 284 (PA171). Radiant heater asset #4232 has bad igniter. CMI found during Dec. PM.

Proposal is to provide and perform the following:

- Remove defective Ignitor and Ignition Control
- Provide and install (1) Ignitor and (1) Ignition Control
- Sissor Lift
- Start up
- Warranty