



Routine Asset# 4494- Electric wall mounted heater/air conditioner in server room is inoperable. Unit is very aged and is most likely in need of a repair by replacement.

Proposal to provide and perform the following:

- Provide and install (1) See Breeze PTAC unit
- Start up
- Warranty

CMI Cost Estimate								
Funding Request								
WV041 Weirton								
Asset# 4494- Electric wall mounted heater								
CSS #17424 - CMI # 8155								
Prepared By: J. Bayne								
2.22.19								
Asset 4494								
P3 Routine								
			Labor			Sub	OHP	
Description	Rate	Hours	Cost	Material	Tax	Total	20%	Total
1. Repair Cost								
1.1 Labor	\$ 98.00	5					\$	490.00
1.2 Pressure Relief valve					\$ -	\$ -	\$ -	\$ 1,067.26
1.3 Shipping							\$	24.00
Sub Total Repair Cost							\$	1,581.26
2. Initial Service Call Investigation								
2.1 Field Review at Site	\$ 98.00	4					\$	392.00
Grand Total							\$	1,973.26