



Repair the following plumbing issues: 1 - AAFES - on demand unit leaking from supply side overflow tube when hot water is used and then shut off - suspect issue with expansion tank; 2 - AMSA - nylon packing in flush lever on Latrine M urinal - deteriorated and protrudes from below lever; 3 - ARC - UH-6 in caged storage - leaking dielectric union on return side prior to valve; 4 - Drill hall Mech Rm - dielectric union on AHU 5 above controls box – leaking

Proposal to provide and perform the following:

- Remove the dielectric fittings and replace with new
- Run new condensate line from water heater to the mop sink