

Additional Funding Request

PA209	CSS# 17481 WO# 7533 Asset# NA											
Description of Repairs	Labor and materials to install 1 Honeywell 5000 style thermostat and 1 Amana PTAC Fan motor.											
Diagnosis: Initial Work Order	PTAC units and a cabinet heater that are not working - Supply Offices - Rooms 139 & 141 PTAC units blowing cold air. Repaired under separate service call and reset switch but they stopped working after a couple of days. Room 113 - ATWAC #2 is only blowing cold air - it could be a problem with the thermostat.											
Diagnostic Fee	<p>\$ 500.00</p> <p>Renick Brothers Labor \$120/hr x 3</p> <p>Travel 70 miles investigative travel/\$140.00</p>											
Additional Labor Cost to Perform Repairs	<p>\$ 720.00</p> <p>Renick Brothers Labor \$120/hr x 6 Travel</p> <p>70 miles repair travel/ \$140.00</p>											
Additional Material Cost to Perform Repairs	<p>\$430.00</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">Honeywell 5000 style digital thermostat Part #TH5320U1001</td> <td style="width: 10%;">1</td> <td style="width: 10%;">\$113.50</td> <td style="width: 10%;">\$113.50</td> </tr> <tr> <td>Amana PTAC replacement blower motor fan Part #0131P00002S</td> <td>1</td> <td>\$176.50</td> <td>\$176.50</td> </tr> </table>				Honeywell 5000 style digital thermostat Part #TH5320U1001	1	\$113.50	\$113.50	Amana PTAC replacement blower motor fan Part #0131P00002S	1	\$176.50	\$176.50
Honeywell 5000 style digital thermostat Part #TH5320U1001	1	\$113.50	\$113.50									
Amana PTAC replacement blower motor fan Part #0131P00002S	1	\$176.50	\$176.50									
Total Cost of Repair	\$ 1,650.00											



ATWAC
45

