



OneCIS Insurance Company

95 Oakwood Rd
Lake Zurich, IL 60047
(855) 593-5115
www.us.bureauveritas.com



June 21, 2019

44110-007211.00

Jane Lew USARC/OMS
7605 US Highway 19 N
Jane Lew, WV 26378-7932

HARD COPY

RE: **Jurisdictional Inspection:**

Jane Lew USARC/OMS
7605 US Highway 19 N
Jane Lew, WV 26378-7932

Thank you for the consideration I received during my visit on May 15, 2019 at your facility listed above. The purpose of the visit was to perform the external inspections of the objects listed below to determine compliance with ASME/National Board rules and regulations. I was accompanied by Jennifer Bailey during my visit.

The inspections were performed on behalf of International Support Group (US Army Reserve Offices).

The following objects were inspected at the time of the visit:

Year Built	Type of object	Jurisdictional Number	NB Number	Recommendation(s)
	Stainless steel	WV020-1	197843	See Below
	Stainless steel	WV020-2	197847	None
	Stainless steel	WV020-3	197897	See Below
	Stainless steel	WV020-4	197846	See Below
1997	Water Tube	WV020-5	72859	None

The following observations were noted during the inspection of this equipment:

Fittings, attachments, and accessible parts were closely examined and found in satisfactory condition with the notable exceptions below.

As a result of this inspection, there were 3 recommendations suggested.

In order for the certificate(s) of operation to be renewed, all code violations must be cleared.

The recommendation(s) made to correct the deficiency(s) are listed below. Please indicate any action(s) taken on these recommendation(s), by calling me at the number listed below.

Based upon this visit, a report of this inspection activity is being forwarded to the governing jurisdiction. That report is requesting new certificates of operation be issued for the object with no adverse conditions noted. The renewal of certificate of operation is being withheld for the objects with code recommendation(s) listed above.

The next inspection is tentatively scheduled to be completed by 07/15/2019.

Recommendations

The following recommendation(s) must be completed before an operating permit can be issued.

No. **2019-06-1** - Complete within 30 days
Laars-WV020-1 located in Boiler Room

Condition: Boiler is out of service, reportedly due to a leak.

Requirement: Investigate/repair leak.

No. **2019-06-2** - Complete within 30 days
Laars-WV020-3 located in Boiler Room

Condition: Relief Valve is installed incorrectly.

Requirement: Replace/reinstall relief valve such that the spindle is in the vertical position.

No. **2019-06-3** - Complete within 30 days
Laars-WV020-4 located in Boiler Room

Condition: Relief valve is installed incorrectly.

Requirement: Replace/reinstall relief valve such that the spindle is in the vertical position.

Please contact me by phone at 571-373-0998 or by e-mail at william.johnson@onecis.com if there are any questions and to clear any recommendations.

Sincerely,

William Garth Johnson

William Garth Johnson
B&M Jurisdictional Specialist

DISTRIBUTION

Cc:

Jamie Merchant, International Support Group
jmerchant@internationalsupportgroup.com

Thomas Kovach, OneCIS Insurance
Thomas.kovach@onecis.com

FILE

This document is advisory in nature. Reports or certificates provided in connection with any state-required boiler or pressure vessel inspection do not mean that all hazards or conditions were controlled at the time of the inspection. No liability is assumed by the information contained in this document.