

Additional Funding Request

Submitted: 1/28/2019

MD013 – access panels for service and isolation of maintenance	CSS #16720 WO#6860
Description of Repairs	HVAC valve and controls need access panels for service & isolation for maintenance.
Original SC Investigative Diagnosis	Waived
Diagnosis: Initial Work Order	S&S will make necessary wall repairs along with cutting out hole and inserting access panel in order to access plumbing valves for future need. S&S will prime and paint wall to a designated spot that makes for nice transition and not obvious, paint will match existing wall color as close as possible.
Explanation of Additional Costs for Repairs	N/A
Additional Material Cost to Perform Repairs	<p>Materials: = \$78.97</p> <p>Roller Cover =1 @ \$5.60 ea= \$5.60 Sanding Block=1 @ \$7.45 ea= \$7.45 Durabond 90 25lb=1 @ \$14.38 ea= \$14.38 6in x 9in white access panel with frame=1 @ \$13.00 ea = \$13.00 1 gal Ultra White Eggshell Paint=1 @ \$34.78 ea= \$34.78 Material Tax = \$3.76</p>
Additional Labor Cost to Perform Repairs	<p>Labor: \$675.00</p> <p>1 General Maintenance Technician /9 hours/ Rate \$75.00 per hour = \$675.00</p>
Total Cost of Repair	\$753.97