

Additional Funding Request

Submitted: 12/10/2018

MD0016 – aqua stat	CSS #Pending WO#6865
Description of Repairs	No heat.
Original SC Investigative Diagnosis	\$200.00
Diagnosis: Initial Work Order	<p>S&S hereby proposes to furnish the labor and materials to complete the following:</p> <p>-S&S will remove and replace aqua stat due to over running temperature. Will perform formal operational checks once installed.</p>
Explanation of Additional Costs for Repairs	N/A
Additional Material Cost to Perform Repairs	<p>Materials: = \$245.87</p> <p>Aqua Stat #L 4006E1067 = \$219.87</p> <p>Tax = \$11.00</p> <p>Shipping: \$15.00</p>
Additional Labor Cost to Perform Repairs	<p>Labor: \$200.00</p> <p>1 HVAC Technician / 2hours/ Rate \$100.00 per hour = \$200.00</p>
Total Cost of Repair	\$645.87