

## Additional Funding Request

Submitted: 12/12/2018

<b>MD021</b> – blower assembly/inducer motor	<b>CSS #16724 WO#6861</b>
Description of Repairs	Heat failure in training building, FC describes heat out for 2 days with frost in interior building.
Original SC Investigative Diagnosis	<b>\$350.00</b> 1 HVAC Technician/3.5hours/ Rate \$100.00 per hour = \$350.00
Diagnosis: Initial Work Order	S&S will return with a new inducer motor for boiler #1.
Explanation of Additional Costs for Repairs	N/A
Additional Material Cost to Perform Repairs	<b>Materials: = \$1,708.16</b> Blower Assy/W383600045/QTY 1 = \$1,579.20 Tax = \$78.96 Shipping = \$50.00
Additional Labor Cost to Perform Repairs	<b>Labor: \$400.00</b> 1 HVAC Technician/4 hours/ Rate \$100.00 per hour = \$400.00
<b>Total Cost of Repair</b>	<b>\$2,458.16</b>