

Additional Funding Request

MD002	CSS# 24508 WO# 12032 Asset# NA															
Description of Repairs	Repair leaking water fountain 1 st floor building 002															
Diagnosis: Initial Work Order	Repair leaking water fountains, 1st floor bldg. 002.															
Diagnostic Fee	<p>\$ 240</p> <p>Labor \$80/hr x 3</p>															
Additional Labor Cost to Perform Repairs	<p>\$ 480</p> <p>Labor \$80/hr x 6</p>															
Additional Cost	<p>\$ 149.46</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%;">1/2" Y Strainer, Threaded ,1/32" Mesh PVC</td> <td style="width: 15%;">1</td> <td style="width: 15%;">\$113.40</td> <td style="width: 15%;">\$113.40</td> </tr> <tr> <td>2 Quarts Paint (See attached detail)</td> <td>1</td> <td>28.38</td> <td>28.38</td> </tr> <tr> <td>TAX</td> <td></td> <td></td> <td>7.68</td> </tr> </table>				1/2" Y Strainer, Threaded ,1/32" Mesh PVC	1	\$113.40	\$113.40	2 Quarts Paint (See attached detail)	1	28.38	28.38	TAX			7.68
1/2" Y Strainer, Threaded ,1/32" Mesh PVC	1	\$113.40	\$113.40													
2 Quarts Paint (See attached detail)	1	28.38	28.38													
TAX			7.68													
Total Cost of Repair	\$ 869.46															



WORK ESTIMATE

CSS #: Work Order #:
Emergency Urgent Routine X

Company Name:	Tidewater, Inc.	Facility ID:	MD002
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g.,	
E-Mail Address:	adam.colopy@tideh2o.net	Classroom/Room #)	
Assigned Technician(s):	JOHN BROWN		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Repair leaking water fountains, 1st floor bldg. 002.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$80	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
Diagnostic			3	\$240.00
1/2" Y Strainer, Threaded , 1/32" Mesh PVC	1	\$113.40		\$113.40
2 Quarts Paint (See attached detail)	1	\$28.38		\$28.38
Labor			6	\$480.00
TAX				\$7.68
SUB-TOTAL COSTS:		Materials Total	\$149.46	Labor \$720.00
		TOTAL		\$869.46

HAYWARD

1/2" Y Strainer, Threaded, 1/32" Mesh, PVC

Item # 3CEN1 Mfr. Model # YS10050TU Catalog Page # 2896 UNSPSC # 40142504

Web Price 1

\$94.50 / each

1

[Add to Cart](#)[+ Add to List](#) Shipping PickuExpected to arrive **Wed. Apr 08**Ship To 43085 ([Change](#))

Shipping Weight 0.98 lbs.

Country of Origin USA | *Country of Origin is subject to change.**Note: Product availability is real-time updated and adjusted continuously. The product will be reserved for you when you complete your order. [More](#)* How can we [improve our Product Images?](#) Compare

Product Details

[View More](#) 

Technical Specs

Item	Y Strainer	Width	1-1/2"
Pipe Size	1/2"	Screen Area	4.19 sq. in.
Connection Type	Threaded	Screen Material	PVC
Housing Material	PVC	Mesh	1/32"
Max. Pressure	150 psi	Gasket Material	FPM
Height	2-61/64"	Blow-off Port	1/2"

 Chat with an Agent


Glen Burnie



Search

**KILZ PREMIUM 1 Qt. White Interior/Exterior Primer, Heavy-Duty**

\$9.67

**Sheen:** Flat/Matte

Flat/Matte

Container Size: 1 QT-Quart

1 GA-Gallon

1 QT-Quart

5 GA-Gallon

Number per Package: 1

1

Find it at Glen Burnie #2501

✓ 7 in stock

Aisle: 04 Bay: 018
See In-Store Map**Check Nearby Stores****\$9.67**

Home



Shop



Account



Stores

...
More

Glen Burnie



Search



BEHR PREMIUM PLUS 1 qt.
#52 White Eggshell Enamel Low
 \$13.98



BEHR Premium Plus

Sheen: EggshellHelp me choose 

Flat/Matte

Eggshell 


Satin

Semi-Gloss

High-Gloss

Container Size: 1 QT - QuartHelp me choose 

8 OZ - Sample

1 QT - Quart 

1 GA - Gallon



5 GA - Gallon

Free delivery on 8oz. paint samples
every day!**\$13.98**

Home



Shop



Account



Stores

000

More



