

Additional Funding Request

Submitted: 2/22/2021

MD002- Steamer not working	CSS #28450 WO# 13461												
Description of Repairs	Steamer not working in DFAC												
Original SC Investigative Diagnosis	NA												
Diagnosis: Initial Work Order	DFAC Steamer Not Working, Electrical Issues												
Explanation of Additional Costs for Repairs	N/A												
Additional Material Cost to Perform Repairs	<p>Materials: \$514.72</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="padding: 2px;">Parts (See Detail)</td><td style="padding: 2px;">1</td><td style="padding: 2px;">\$497.15</td><td style="padding: 2px;">\$497.15</td></tr> <tr> <td style="padding: 2px;">Shipping</td><td style="padding: 2px;">1</td><td style="padding: 2px;">\$17.57</td><td style="padding: 2px;">\$17.57</td></tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	Parts (See Detail)	1	\$497.15	\$497.15	Shipping	1	\$17.57	\$17.57
ITEM	QUANTITY	UNIT PRICE	TOTAL										
Parts (See Detail)	1	\$497.15	\$497.15										
Shipping	1	\$17.57	\$17.57										
Additional Labor Cost to Perform Repairs	<p>Labor: \$700 Plumber Labor Tech/7 hours/Rate \$100.00 per hour = \$700.00</p>												
Total Cost of Repair	\$1,214.72												