

Additional Funding Request

Submitted: 7/9/20

MD002 – Units not cooling	CSS #20482 WO# 11765																
Description of Repairs	Repairs to 3 cold storage appliances in the kitchen, bldg 1. All not cooling to temp.																
Original SC Investigative Diagnosis	\$350.00																
Diagnosis: Initial Work Order	Units still not cooling since repair 10/28/19 WO 10592. S&S was onsite and found that the blower motor was in operation but was constantly running. S&S proposes to remove and replace the control head and relay hybrid. S&S will then complete a system check to ensure everything is running properly.																
Explanation of Additional Costs for Repairs	N/A																
Additional Material Cost to Perform Repairs	<p>Materials: \$855.82</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: center; padding: 2px;">QUANTITY</th> <th style="text-align: center; padding: 2px;">UNIT PRICE</th> <th style="text-align: center; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="padding: 2px;">Relay Hybrid/ 192226</td> <td style="text-align: center; padding: 2px;">1</td> <td style="text-align: center; padding: 2px;">\$105.94</td> <td style="text-align: center; padding: 2px;">\$105.94</td> </tr> <tr> <td style="padding: 2px;">Control Head/ 235741</td> <td style="text-align: center; padding: 2px;">1</td> <td style="text-align: center; padding: 2px;">\$649.88</td> <td style="text-align: center; padding: 2px;">\$649.88</td> </tr> <tr> <td style="padding: 2px;">Shipping</td> <td style="text-align: center; padding: 2px;">1</td> <td style="text-align: center; padding: 2px;">\$100.00</td> <td style="text-align: center; padding: 2px;">\$100.00</td> </tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	Relay Hybrid/ 192226	1	\$105.94	\$105.94	Control Head/ 235741	1	\$649.88	\$649.88	Shipping	1	\$100.00	\$100.00
ITEM	QUANTITY	UNIT PRICE	TOTAL														
Relay Hybrid/ 192226	1	\$105.94	\$105.94														
Control Head/ 235741	1	\$649.88	\$649.88														
Shipping	1	\$100.00	\$100.00														
Additional Labor Cost to Perform Repairs	<p>Labor: \$1,000.00</p> <p>Refrigeration Labor/10 hours/Rate \$100.00 per hour = \$1,000.00</p>																
Total Cost of Repair	\$2,205.82																