

Additional Funding Request

MD003 – Boiler	Maximo WO # 6470 CSS# 16337 Asset #1861
Description of Repairs	Labor and materials to install the gas pressure switch (which is already on site) for boiler #2.
Diagnosis: Initial Work Order	BOTH Boilers would not light off for proving of safety devices.
Explanation of Additional Costs for Repairs	Labor and material to repair the boiler.
Investigative Diagnosis from SC	\$400.00
Additional Material Cost to Perform Repairs	\$0
Additional Labor Cost to Perform Repairs	1 technician (\$100.00 an hour x 4 hours) = \$400.00
Total Cost of Repair	\$800.00



S&S MECHANICAL

S&S Mechanical

Location: PFC Carl Vernon Sheridan USARC
5515 Liberty Heights Ave
Baltimore, MD 21207

Proposal Submitted to: Karlee Demain

Project: WO-6470-Boiler #2

Office # 301-574-1555

Fax # 301-574-1558

seth@sandsmidatlantic.com
sandsmidatlantic.com

S&S was on site and diagnosed that boiler #2 needs the gas pressure switch installed:

Diagnoses Labor: \$400.00

1 HVAC Technician/4hours/ Rate \$100.00 per hour = \$400.00

S&S will return to install the gas pressure switch (which is already on site) for boiler #2.

Labor: \$400.00

1 HVAC Technician/4hours/ Rate \$100.00 per hour = \$400.00

Full Estimated total: \$800.00

Payments to be made as follows: 15 days upon approved invoice

Respectfully submitted: Brian Davis/Molly King Dated: 12/20/2018

