

## Additional Funding Request

Submitted: 7/9/20

<b>MD003</b> – OMS shop boiler repairs	<b>CSS #22942 WO# 11441</b>			
Description of Repairs	This boiler would not lite off for operational testing because of the check valve in the make up water. This is for the OMS Shop Boiler for repair to pass inspection.			
Original SC Investigative Diagnosis	<b>\$450.00</b>			
Diagnosis: Initial Work Order	S&S was onsite and diagnosed that the Honeywell pressure switch and gas pressure safe switch were faulty and would need replacement. S&S will remove and replace the pressure switch and safe switch on the boiler. S&S will then complete a system check to ensure everything is running as intended.			
Explanation of Additional Costs for Repairs	N/A			
Additional Material Cost to Perform Repairs	<b>Materials: \$709.08</b>			
	<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>
	Honeywell Pressure Switch/ 235856	1	\$155.64	\$155.64
	Gas Pressure Safe Switch	1	\$453.44	\$453.44
	Shipping	1	\$100.00	\$100.00
Additional Labor Cost to Perform Repairs	<b>Labor: \$1,000.00</b> Plumber Labor Tech/10 hours/Rate \$100.00 per hour = \$1,000.00			
<b>Total Cost of Repair</b>	<b>\$2,159.08</b>			