

Additional Funding Request

Submitted: 2/11/2020

MD013 – CAC card reader	CSS #23927 WO#11791			
Description of Repairs	CAC reader at main entrance to facility not working.			
Original SC Investigative Diagnosis	NA			
Diagnosis: Initial Work Order	Based on LoCurrent’s records, the Reader on the Front Door is 5 years or older, additionally, they spoke with POC Glenn Umberger who described the symptoms he is experiencing. LoCurrent will complete quote for a replacement Reader instead of charging the \$450 to diagnose what they already know is wrong.			
Explanation of Additional Costs for Repairs	N/A			
Additional Material Cost to Perform Repairs	Materials: \$1,250.00			
	ITEM	QUANTITY	UNIT PRICE	TOTAL
	Veridt Multimode Biometric Reader Part #900W2030	1	\$1,450.00	\$1,450.00
	Core Discount Rebate		(\$200.00)	(\$200.00)
	TOTAL			\$1,250.00
Additional Labor Cost to Perform Repairs	Labor: \$600.00 1 Labor Techs/8 hours each/Rate \$75.00 per hour = \$600.00			
Total Cost of Repair	\$1,850.00			