

Additional Funding Request

WITH INVOICE

Submitted: **7/25/2022**

MD013-Hose bib-OMS bldg	CSS #1645 WO#18469								
Description of Repairs	7/18 Leaking hose bib beside bay door on OMS building. Shut water off and took apart hose bib, the rubber has worn away and no longer sealing. Ordering a rebuild kit and will return. 7/22 Rebuilt hose hydrant using rebuild kit. Tested that hydrant works and no longer leaks. Work complete.								
Original SC Investigative Diagnosis	NA								
Diagnosis: Initial Work Order	Repair Hose Bib on OMS building, Leaking behind shut off valve								
Explanation of Additional Costs for Repairs									
Additional Material Cost to Perform Repairs	<p>Materials: \$ 111.70</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">Rebuild Kit</td> <td style="text-align: left; padding: 2px;">1</td> <td style="text-align: left; padding: 2px;">\$111.70</td> <td style="text-align: left; padding: 2px;">\$111.70</td> </tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	Rebuild Kit	1	\$111.70	\$111.70
ITEM	QUANTITY	UNIT PRICE	TOTAL						
Rebuild Kit	1	\$111.70	\$111.70						
Additional Labor Cost to Perform Repairs	<p>Labor: \$600.00 6 hours each/Plumbing Rate \$100.00 per hour = \$600.00</p>								
Total Cost of Repair	\$711.70								