

Additional Funding Request

WITH INVOICE

Submitted: 4/28/22

MD013 Toilet Leaking	CSS #25 WO#17315											
Description of Repairs	Repair Toilet leaking in upstairs ladies' room and stopped up sink in downstairs ladies room											
Original SC Investigative Diagnosis	\$NA											
Diagnosis: Initial Work Order	Repair Toilet leaking in upstairs ladies' room and stopped up sink in downstairs ladies Room											
Explanation of Additional Costs for Repairs	N/A											
Additional Material Cost to Perform Repairs	Materials: \$276.42 <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">Parts detailed on invoice</td> <td style="text-align: left; padding: 2px;">1</td> <td style="text-align: left; padding: 2px;">\$276.42</td> <td style="text-align: left; padding: 2px;">\$276.42</td> </tr> </tbody> </table>				ITEM	QUANTITY	UNIT PRICE	TOTAL	Parts detailed on invoice	1	\$276.42	\$276.42
ITEM	QUANTITY	UNIT PRICE	TOTAL									
Parts detailed on invoice	1	\$276.42	\$276.42									
Additional Labor Cost to Perform Repairs	Labor: \$500.00 5 hours each/Plumbing Rate \$100.00 per hour = \$500.00											
Total Cost of Repair	\$776.42											