

## Additional Funding Request

Submitted: 6/14/2021

<b>MD013- Main AHU</b>	<b>CSS # 30528 WO#14178</b>			
Description of Repairs	S&S proposes to remove and replace the voltage monitor and current switch on the AHU in the mechanical room. S&S will then complete a system check to ensure the system is now running properly.			
Original SC Investigative Diagnosis	<b>\$400.00</b>			
Diagnosis: Initial Work Order	Main Mechanical room AHU is operational but has a VFD alarm			
Explanation of Additional Costs for Repairs	N/A			
Additional Material Cost to Perform Repairs	<b>Materials: NA</b>			
	<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>
	Parts detailed in quote	1	\$288.88	\$288.88
Additional Labor Cost to Perform Repairs	<b>Labor: \$800.00</b> 8 hours each/Rate \$100.00 per hour = \$800.00			
<b>Total Cost of Repair</b>	<b>\$1488.88</b>			