

Additional Funding Request

Submitted: 09/13/2021

MD013- MEP Light asset 3Y262	CSS # 34219 WO# 15017								
Description of Repairs	S&S found the LED driver in MEP light asset# 3Y262 was bad and will need to be replaced. S&S proposes to remove and replace the LED driver								
Original SC Investigative Diagnosis	\$200								
Diagnosis: Initial Work Order	MEP light not working Asset# 3Y262.								
Explanation of Additional Costs for Repairs	N/A								
Additional Material Cost to Perform Repairs	<p>Materials: \$72.52</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">LED Driver</td> <td style="text-align: left; padding: 2px;">72.52</td> <td style="text-align: left; padding: 2px;">1</td> <td style="text-align: left; padding: 2px;">72.52</td> </tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	LED Driver	72.52	1	72.52
ITEM	QUANTITY	UNIT PRICE	TOTAL						
LED Driver	72.52	1	72.52						
Additional Labor Cost to Perform Repairs	<p>Labor: \$400.00 4 hours each/Electrical Rate \$100.00 per hour = \$400.00</p>								
Total Cost of Repair	\$672.52								