

Additional Funding Request

Submitted: 10/20/2021

MD013- CAC Reader	CSS #32911 WO#15133											
Description of Repairs	As per your request LoCurrent Systems is pleased to Diagnose/Repair if possible CAC Reader, Rear Door Main Building, at the Gaithersburg, MD USARC (MD013). The cost for the above mentioned is \$450.00.											
Original SC Investigative Diagnosis	\$450.00											
Diagnosis: Initial Work Order	CAC reader not working. Rear door Main Building Diagnose and repair											
Explanation of Additional Costs for Repairs	LoCurrent Systems is pleased to provide a quotation for the Replacement of (1) DRM Module, and (1) Electric Strike at Gaithersburg, MD (MD013). This includes configuration, programming and system testing.											
Additional Material Cost to Perform Repairs	Materials: \$ 837.00 <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">Parts (See detail in quote)</td> <td style="text-align: center; padding: 2px;">1</td> <td style="text-align: center; padding: 2px;">\$837.00</td> <td style="text-align: center; padding: 2px;">\$837.00</td> </tr> </tbody> </table>				ITEM	QUANTITY	UNIT PRICE	TOTAL	Parts (See detail in quote)	1	\$837.00	\$837.00
ITEM	QUANTITY	UNIT PRICE	TOTAL									
Parts (See detail in quote)	1	\$837.00	\$837.00									
Additional Labor Cost to Perform Repairs	Labor: \$600.00 8 hours each/ Rate \$75.00 per hour = \$600.00											
Total Cost of Repair	\$1,887.00											