

Over and Above Estimate

Region: 5

Location: MD013

CSS #: PENDING

Maximo Work Order No.: 13167

Date Issued: 11/18/2020

Original Description: Boiler has Fault Code E13 -Auxiliary Sensor Failure. Boiler needs new controller. S&S will install new controller for boiler.

Non Pre-Priced Estimate:

Quantity	Line Item Number	Description	Labor Hours	Tax Ship	Labor Rate	Materials	Equipment	Total
1	N/A	Controller for boiler				\$3,206.32		\$3,206.32
1	N/A	Diagnostic Fee			\$450.00			\$450.00
1	N/A	HVAC Labor Rate	8		\$100.00			\$800.00

Note: RS Means (Pre-Priced) not used in compiling this estimate.

Note: Subcontractor quote attached.

Estimate Summary:

Labor Hours	Labor Cost	Material Cost		Total Cost	CE Factor	Total Estimate
8	\$1,250.00	\$3,206.32		\$4,456.32	100%	\$4,456.32