

Additional Funding Request

Submitted: 1.21.2020

MD013 – more time needed to tune boiler	CSS #22493 WO #11311
Description of Repairs	Need to have boiler tuned.
Diagnosis: Initial Work Order	S & S will need more time allotted to tune the boiler at MD013.
Diagnostic Fee	Diagnostic Total: NA
Explanation of Additional Costs for Repairs	NA
Additional Labor Cost to Perform Repairs	Labor: \$1,200.00 HVAC Labor Rate /12 hours/ Rate \$100.00 per hour = \$1,200.00
Additional Material Cost to Perform Repairs	NA
Total Cost of Repair	\$1,200.00