

Additional Funding Request

Submitted: 1/23/2020

MD013	CSS #23064 WO#11574																								
Description of Repairs	No heat in offices 123-127.																								
Original SC Investigative Diagnosis	NA																								
Diagnosis: Initial Work Order	S & S proposes to furnish and install the following: S & S will remove and replace the actuator in room 123. S & S will replace six new glass gaskets. S & S will then test the operation to ensure everything is working properly.																								
Explanation of Additional Costs for Repairs	N/A																								
Additional Material Cost to Perform Repairs	<p>Materials: \$590.78</p> <table border="1"> <thead> <tr> <th>ITEM</th><th>QUANTITY</th><th>UNIT PRICE</th><th>TOTAL</th></tr> </thead> <tbody> <tr> <td>Actuator / 227023</td><td>1</td><td>\$231.35</td><td>\$231.35</td></tr> <tr> <td>Sight glass kit/ 227046</td><td>1</td><td>\$142.28</td><td>\$142.28</td></tr> <tr> <td>Glass gasket/ 227047</td><td>1</td><td>\$46.16</td><td>\$46.16</td></tr> <tr> <td>Tax</td><td>1</td><td>\$20.99</td><td>\$20.99</td></tr> <tr> <td>Shipping</td><td>1</td><td>\$150.00</td><td>\$150.00</td></tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	Actuator / 227023	1	\$231.35	\$231.35	Sight glass kit/ 227046	1	\$142.28	\$142.28	Glass gasket/ 227047	1	\$46.16	\$46.16	Tax	1	\$20.99	\$20.99	Shipping	1	\$150.00	\$150.00
ITEM	QUANTITY	UNIT PRICE	TOTAL																						
Actuator / 227023	1	\$231.35	\$231.35																						
Sight glass kit/ 227046	1	\$142.28	\$142.28																						
Glass gasket/ 227047	1	\$46.16	\$46.16																						
Tax	1	\$20.99	\$20.99																						
Shipping	1	\$150.00	\$150.00																						
Additional Labor Cost to Perform Repairs	<p>Labor: \$1,000.00</p> <p>HVAC Labor 10 hours/Rate \$100.00 per hour = \$1,000.00</p>																								
Total Cost of Repair	\$1,590.78																								