

Additional Funding Request

Submitted: 11/16/2020

MD013 – no hot water in training building	CSS #27421 WO#13135																
Description of Repairs	NO HOT WATER IN TRAINING BUILDING. This is an ongoing issue with this water heater, please make repairs to correct this issue.																
Original SC Investigative Diagnosis Fee	\$400.00																
Diagnosis: Initial Work Order	S&S was onsite and found the building had no hot water because heater #1 was not able to be controlled due to the screen and control buttons being locked up. Changed the heater over since heater #2 is not being used allowing hot water to building. S&S proposes to replace the display overlay in heater # 2 and check the operation to ensure everything is working properly. S&S was onsite replacing the overlay and found the display module will also need to be replaced. *Module lead time is 5 days.																
Explanation of Additional Costs for Repairs	N/A																
Additional Material Cost to Perform Repairs	<p>Materials: \$432.07</p> <table border="1"> <thead> <tr> <th>ITEM</th> <th>QUANTITY</th> <th>UNIT PRICE</th> <th>TOTAL</th> </tr> </thead> <tbody> <tr> <td>Materials (see attached detail on quote)</td> <td></td> <td></td> <td>\$382.00</td> </tr> <tr> <td>Shipping</td> <td>1</td> <td>\$50.00</td> <td>\$50.00</td> </tr> <tr> <td>Total</td> <td></td> <td></td> <td>\$432.07</td> </tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	Materials (see attached detail on quote)			\$382.00	Shipping	1	\$50.00	\$50.00	Total			\$432.07
ITEM	QUANTITY	UNIT PRICE	TOTAL														
Materials (see attached detail on quote)			\$382.00														
Shipping	1	\$50.00	\$50.00														
Total			\$432.07														
Additional Labor Cost to Perform Repairs	<p>Labor: \$1,200.00 Plumbing Labor Rate / \$100.00 hourly rate / 12 hours = \$1,200.00</p>																
Total Cost of Repair	\$2,032.07																