

Additional Funding Request Corrective Maintenance

MD016 –Compressor	CSS # 15610 WO# 6005 Asset # 2031
Description of Repairs	S&S will remove and replace the compressor found bad in the mini split unit in 121C:
Diagnosis: Initial Work Order CSS# 15610	Room 121C Mini split not working .Found during PM
Explanation of Additional Costs for Repairs	S&S will remove and replace the compressor found bad in the mini split unit in 121C:
Additional Labor Cost to Perform Repairs	<p>Labor: \$600.00</p> <p>1 HVAC Technician / 6hours/ Rate \$100.00 per hour = \$600.00</p>
Additional Material Cost to Perform Repairs	<p>Materials: = \$1,174.35</p> <p>Compressor #623-126-8028 = \$1,094.61</p> <p>Tax = \$54.74</p> <p>Shipping: \$25.00</p>
Total cost	\$1,774.35
-\$250 PM cost	-\$250
Total Cost of Repair	\$1,524.35

