

Additional Funding Request

Submitted: 3/1/2019

MD016 – broken window	CSS #17834 WO#7912												
Description of Repairs	Window was broken in front door area.												
Original SC Investigative Diagnosis	Diagnoses Labor: \$75.00												
Diagnosis: Initial Work Order	<p>S&S proposes to furnish the labor and material necessary for the completion of the following:</p> <ul style="list-style-type: none"> - To remove the broken window and replace with new. - Work will take place during normal business hours. 												
Explanation of Additional Costs for Repairs	N/A												
Additional Material Cost to Perform Repairs	<p>Materials: \$1,114.74</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="padding: 2px;">68-1/4" x 25-1/4" wire glass</td><td style="padding: 2px;">1.00</td><td style="padding: 2px;">\$1,061.66</td><td style="padding: 2px;">\$1,061.66</td></tr> <tr> <td style="padding: 2px;">tax</td><td style="padding: 2px;">1.00</td><td style="padding: 2px;">\$53.08</td><td style="padding: 2px;">\$53.08</td></tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	68-1/4" x 25-1/4" wire glass	1.00	\$1,061.66	\$1,061.66	tax	1.00	\$53.08	\$53.08
ITEM	QUANTITY	UNIT PRICE	TOTAL										
68-1/4" x 25-1/4" wire glass	1.00	\$1,061.66	\$1,061.66										
tax	1.00	\$53.08	\$53.08										
Additional Labor Cost to Perform Repairs	<p>Labor: \$300.00 General Maintenance Labor Tech/4hours/Rate \$75.00 per hour = \$300.00</p>												
Total Cost of Repair	\$1,489.74												