

Region: 5

Location: MD019

CSS #: 22111

Maximo Work Order No.: 11254

Asset #: NA

Date Issued: 10/24/19

Original Description:

POV pole light ts are not working properly . I have reset the timer basedon the change of seasons but this did not remedy the issue.

Repairs Needed:

S & S proposes to furnish and install the following:

S & S will remove and replace two 30 amp contactors.

S & S will then check the operation to ensure everything is running properly.

RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	Materials (See attached detail)	--	--	\$2,265.64	--	\$2,265.64
--	NA	Shipping and Tax	--	--	\$184.08	--	\$184.08
--	NA	S&S Labor (includes Diagnostic)	10	\$100.00	--	--	\$1,000.00
--	NA	TW Oniste Mechanical Assistance	4	80	--	--	\$320.00

Estimate Summary:

Labor Hours	Labor Cost	Materials	Equipment	Total Cost	CE Factor	Total Estimate
14	\$1,320.00	\$2,449.72	\$0.00	\$3,769.72	100%	\$3,769.72



S&S MECHANICAL

S&S Mechanical
4845 South Crain Highway
Upper Marlboro, MD 20772

Tel. 1 - (301) 574-1555
Fax. 1 - (301) 574-1558
www.sandsmidatlantic.com

CUSTOMER QUOTATION NO. 138

Tidewater, Inc.
Tidewater, Inc
6625 Selnick Dr.
Suite A
Elkridge MD 21075

Quote Name: 11254
Quote No: 138
Site: MD019 Greenspring Avenue
Site Contact:
Salesperson: Lindsay Ruby
Created Date: 12/12/2019
Valid For: 30 Day(s)

WO# 11254

CSS Ticket Number: 22111

Problem: POV pole lights are not working properly . I have reset the timer based on the change of seasons but this did not remedy the issue.

S & S proposes to furnish and install the following:

S & S will remove and replace two 30 amp contactors.

S & S will then check the operation to ensure everything is running properly.

Service

Item	Quantity	Unit Price	Total
Diagnostic	1.00	\$400.00	\$400.00
30 amp Contactors	1.00	\$1,681.56	\$1,681.56
Tax	1.00	\$84.08	\$84.08
Shipping	1.00	\$100.00	\$100.00
Electrical Labor Rate	6	\$100.00	\$600.00
		Sub-Total ex Tax	\$2,865.64
		Tax	\$0.00
		Total inc Tax	\$2,865.64

Labor	\$600.00
Materials	\$2,265.64
Sub-Total ex Tax	\$2,865.64
Tax	\$0.00
Total inc Tax	\$2,865.64

CAPITAL ELECTRIC
8511 PEPCO PL
UPPER MARLBORO, MD 20772-2500
301-909-6500 Fax 301-736-1361

nichon.skinner@capitalelectricsupply.com

QUOTE TO:
S&S FABRICATORS INC.
4845 SOUTH CRAIN HWY
UPPER MARLBORO, MD 20772-3109
240-882-1660

Quotation

QUOTE DATE	QUOTE NUMBER
12/04/19	S039014708
	PAGE NO.
1 of 1	

SHIP TO:
S&S FABRICATORS INC.
4845 SOUTH CRAIN HWY
UPPER MARLBORO, MD 20772-3109
240-882-1660

CUSTOMER NUMBER	CUSTOMER ORDER NUMBER		JOB NAME	QUOTED TO	
SALESPERSON	SHIP VIA		FREIGHT ALLOWED	EXPIRATION DATE	
NICHON SKINNER	WC WILL-CALL		No	11:59pm ET 01/03/20	
ORDER QTY	UPC	DESCRIPTION	UNIT PRICE	U	EXT PRICE
2ea	78211612456	C-H C30CNE20A0 30A LTG CONT	700.650	e	1401.30


TERMS & CONDITIONS

This order is subject to Company Terms and Conditions of Sale, which provisions shall govern in the event of any conflict with any Terms or Conditions of Purchaser's proposal, purchase order or other documents. All quotes/bids for Pipe and Wire are good for the date of the bid only. No extension of the pricing of these items is authorized by any employee of the Company without express written consent in the form of an official letter or signed acknowledgement of an Officer of the Company.

TAXES NOT INCLUDED

Subtotal	1401.30
S&H CHGS	0.00
Amount Due	1401.30

VA 09 07 &



Place Auxiliary Switch on
LEFT SIDE for use as NO

EATON | Cutler-Hammer

C30CNE LIGHTING CONTACTOR

Coil Terminal Wire Range: #18 - 14 AWG
60/75°C Copper Wire Only
Torque: 15 lbs-in

See Coil for Control
Voltage & Frequency

MADE IN U.S.A.



Place Auxiliary Switch on
RIGHT SIDE for use as NC

A153
IND. CONT. EQ.
120V 60Hz / 110V 50Hz

EATON | Cutler-Hammer
C30CN cUL US LISTED CE
A153
IND. CONT. EQ.
VA 09 07 &

A1

A2

