

Additional Funding Request Corrective maintenance

MD020 Exhaust fan motor	CSS #15608 WO#6017
Description of Repairs	<p>S&S hereby proposes to furnish the labor and materials to complete the following:</p> <p>-S&S will remove and replace exhaust fan motor found bad in Men's shower area:</p>
Diagnosis: Initial Work Order CSS# 15608	Exhaust fan not working in Men's shower area
Explanation of Additional Costs for Repairs	<p>-S&S hereby proposes to furnish the labor and materials to complete the following:</p> <p>-S&S will remove and replace exhaust fan motor found bad in Men's shower area:</p> <p>.</p>
Additional Labor Cost to Perform Repairs	<p>Labor: = \$300.00</p> <p>1 HVAC Technician /3hours/ Rate \$100.00 per hour = \$300.00</p>
Additional Material Cost to Perform Repairs	<p>Materials: = \$363.32</p> <p>Isolators #2NPAl = \$6.33</p> <p>Tax = \$0.32</p> <p>Shipping = \$10.98</p> <p>Fan Motor = \$305.42</p> <p>Tax = \$15.27</p>

	Shipping: \$25.00
Total cost	\$ 663.32
-\$250 PM LoL	\$250
Total	\$ 413.32