

Additional Funding Request
Additional work required to complete job

MD020 Exhaust fan motor	CSS #15608 WO#6017
Description of Repairs	<p>S&S hereby proposes to furnish the labor and materials to complete the following: While replacing fan motor it was discovered the blower wheel needs to be replaced</p> <p>-S&S will remove and replace blower wheel found bad in Men's shower area:</p>
Diagnosis: Initial Work Order CSS# 15608	Exhaust fan not working in Men's shower area
Explanation of Additional Costs for Repairs	<p>-S&S hereby proposes to furnish the labor and materials to complete the following:</p> <p>-S&S will remove and replace blower wheel found bad in Men's shower area:</p> <p>.</p>
Additional Labor Cost to Perform Repairs	<p>Labor: = \$300.00</p> <p>1 HVAC Technician /3hours/ Rate \$100.00 per hour = \$300.00</p>



Additional Material Cost to Perform Repairs	Materials: = \$89.98 Blower Wheel = \$61.90 Tax = \$3.08 Shipping = \$25.00
Total cost	\$389.98