

Additional Funding Request

Submitted: 11/3/2020

MD020 – front door glass repaired/replaced	CSS #27431 WO# 13138												
Description of Repairs	Need to have the front door glass replaced/ repaired.												
Original SC Investigative Diagnosis	\$201.00												
Diagnosis: Initial Work Order	S&S proposes to remove and install new 25" x 77" glass on front door.												
Explanation of Additional Costs for Repairs	N/A												
Additional Material Cost to Perform Repairs	<p>Materials: \$358.28</p> <table border="1"> <thead> <tr> <th>ITEM</th><th>QUANTITY</th><th>UNIT PRICE</th><th>TOTAL</th></tr> </thead> <tbody> <tr> <td>25" X 77" TEMPERED UNIT - INSULATED UNITS CLEAR TEMPERED INSULATED UNIT 1" THICK</td><td>1</td><td>\$358.28</td><td>\$358.28</td></tr> <tr> <td></td><td></td><td></td><td></td></tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	25" X 77" TEMPERED UNIT - INSULATED UNITS CLEAR TEMPERED INSULATED UNIT 1" THICK	1	\$358.28	\$358.28				
ITEM	QUANTITY	UNIT PRICE	TOTAL										
25" X 77" TEMPERED UNIT - INSULATED UNITS CLEAR TEMPERED INSULATED UNIT 1" THICK	1	\$358.28	\$358.28										
Additional Labor Cost to Perform Repairs	<p>Labor: \$320.00 General Maintenance Labor Tech/4 hours/Rate \$80.00 per hour = \$320.00</p>												
Total Cost of Repair	\$879.28												