

## Additional Funding Request

Submitted: 9/20/2019

<b>MD020 – toilets</b>	<b>CSS #21462 WO#11052</b>
Description of Repairs	<b>Replace seals in 10 toilets, men's RR, after turning main water valve on, S&amp;S noticed that the seals are dried out &amp; need replacing to keep toilets from leaking.</b>
Diagnosis: Initial Work Order	<p>S&amp;S proposes to furnish the labor and material necessary for the completion of the following</p> <ul style="list-style-type: none"> <li>- S&amp;S proposes to replace the following materials in the 2nd floor men's room.</li> <li>- S&amp;S will check the operation to ensure the system is running properly.</li> <li>- Work will take place during normal business hours.</li> </ul>
Explanation of Additional Costs for Repairs	
Investigative Diagnosis fee from SC	<b>N/A</b>
Additional Material Cost to Perform Repairs	<p><u>Materials: \$732.60</u></p> <p>Sloan Valve /111/ \$177.74  Sloan Valve /186/ \$177.74  Sloan Kit /A-41/ \$123.50  Sloan Kit /A-43/ \$123.50  Tax: \$30.12  Shipping: \$100.00</p>
Additional Labor Cost to Perform Repairs	<p><b><u>Labor: \$500</u></b>  1 Plumbers /5 Hours/\$100.00 rate= \$500.00</p>
<b>Total Cost</b>	<b>\$1,232.60</b>