

## Additional Funding Request

CM

<b>MD021 Boiler 3</b>	<b>CSS #16132 WO#6426 Asset #</b>
Description of Repairs	S&S hereby diagnosed that Boiler #3 needs a new expansion module:
Diagnosis: Initial Work Order CSS# <b>16132</b>	S&S hereby diagnosed that Boiler #3 needs a new expansion module:  Both Boilers are down .No heat in building  During PM found bad display module
Explanation of Additional Costs for Repairs	<u>Materials:</u> = \$335.10  Expansion Module # 383-600-060 = \$319.14  Tax = \$15.96  Shipping: \$0.00  **Part has 3 week lead time**  .
Additional Labor Cost to Perform Repairs	S&S hereby proposes to remove and install new expansion module for Boiler #3:  <u>Labor:</u> 1 HVAC Technician /3hours/ Rate \$100.00 per hour = \$300.00
Original SC Cost	<u>Diagnostic Labor:</u> 1 HVAC Technician /3hours/ Rate \$100.00 per hour = \$300.00



Additional Material Cost to Perform Repairs	\$ <u>Full service estimated total: \$935.10</u>
-\$250 PM credit	-\$250
<b>Total cost</b>	<b>\$ 685.10</b>