

## Additional Funding Request

<b>MD021</b>	<b>CSS #27104 WO# 12927</b> <b>December 11, 2020</b>
Description of Repairs	Repair (3) high bay lights in OMS building, in first bay area, Not coming on .
Diagnosis: Initial Work Order	S&S proposes to replace 3 bay high lights in OMS building. POC is Mr. Nathan Rigney 540 333 0154.
Original SC diagnosis	<b>\$450.00</b>
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	<b>\$600.00</b> Electrical Labor Rate, see quote
Additional Material Cost to Perform Repairs	<b>\$296.64</b> See details on attached quote
PM Credit	<b>NA</b>
Total Cost	<b>Total = \$1,346.64</b>