

Additional Funding Request

Submitted: 11/09/2021

MD021 -#1 Boiler controller	CSS #33187 WO#15386
Description of Repairs	S&S herby proposes to remove & replace the control module on Boiler #1. S&S will then complete a system check to ensure system is running properly.
Diagnosis: Initial Work Order	S&S herby proposes to remove & replace the control module on Boiler #1. S&S will then complete a system check to ensure system is running properly.
Explanation of Additional Costs for Repairs	
Investigative Diagnosis fee from SC	Diagnostic Total: CMI Paid diagnostic troubleshooting
Additional Material Cost to Perform Repairs	Control module \$ 414.96 + \$60 shipping
Additional Labor Cost to Perform Repairs	Labor: \$400 1 HVAC Technician/4 Hours/\$100.00 rate= \$400.00
Total Cost	\$874.96